

Annex D Selected Community Consultation Responses



Figure D.1 Runoff Down Staircase in Roseville during February 2020 storm (photo courtesy H. Bersten)



Figure D.2 Ponding on street in Roseville Chase during February 2020 storm (photo courtesy A.Adamovich)



Figure D.3 Runoff into property in Roseville Chase during February 2020 storm (photo courtesy A.Adamovich)



Figure D.4 Runoff into property in Roseville during February 2020 storm (photo courtesy R.Hughes)